

Section 18 North, Range 11.15 East of 2nd Meridian

Post	Bearing	Distance	Course	Point	Quality of the Soil
A	Recd	14	S 38 E 13		
B	Hickory	13	S 6 N 23		
C	do	12	S 17 E 21		
D	do	20	S 21 N 32		
E	Hickory	13	S 33 E 46		
F	Recd	14	S 48 N 42		
G	Recd	14	S 68 E 32		
H	Sugar	12	S 50 N 20		
I	B. Ash	6	S 43 E 10		
J	Elm	15	S 52 N 48		
K	do				
L	do				
M	do				
N	do				
O	do				
P	do				
Q	do				
R	do				
S	do				
T	do				
U	do				
V	do				
W	do				
X	do				
Y	do				
Z	do				

Interior Section Corners

Section	Bearing	Distance	Course	Point	Quality of the Soil
26.27.34.35	Hickory	15	S 60 E 6		
12.23.24.25	do	30	S 30 E 12		
10.15.22.23	do	20	S 29 E 32		
10.11.14.15	do	08	S 31 N 34		
9.3.10.11	do	24	S 51 E 26		
27.28.33.34	do	15	S 24 N 23		
21.22.27.28	do	12	S 65 E 30		
15.16.21.22	do	12	S 45 E 20		
7.10.15.16	do	10	S 54 N 14		
3.4.9.10	do	12	S 60 N 25		
28.29.32.33	do	12	S 16 E 20		
20.21.28.29	do	12	S 50 E 23		
16.17.20.21	do	12	S 57 N 24		
8.9.14.15	do	15	S 45 E 22		
4.5.8.9	do	11	S 65 E 23		
29.30.31.32	do	13	S 10 N 24		
19.20.29.30	do	15	S 30 N 7		
17.18.19.20	do	10	S 41 E 24		
7.8.17.18	do	20	S 47 N 30		
5.6.7.8	do	11	S 67 E 22		
	do	15	S 27 N 25		

Interior Quarter Section Corners

Section	Bearing	Distance	Course	Point	Quality of the Soil
1 to 2	do	18	S 41 E 25		
2	do	10	S 24 N 36		
3	do	15	S 35 E 4		
4	do	12	S 10 N 13		
5	do	15	S 61 N 7		
6	do	15	S 75 E 49		
7	do	48	S 40 E 15		
8	do	15	S 75 N 32		
9	do	24	S 20 E 47		
10	do	10	S 20 N 20		
11	do	30	S 66 N 12		
12	do	14	S 71 E 16		
13	do	15	S 62 N 6		
14	do	16	S 34 E 7		
15	do	14	S 48 E 18		
16	do	6	S 48 N 24		
17	do	15	S 41 N 20		
18	do	10	S 50 E 20		
19	do	15	S 30 E 21		
20	do	14	S 25 N 22		
21	do	15	S 46 E 30		
22	do	8	S 46 N 26		
23	do	4	S 55 E 33		
24	do	6	S 13 N 12		
25	do	24	S 48 E 25		
26	do	18	S 21 N 32		
27	do	24	S 35 E 30		
28	do	12	S 44 N 31		
29	do	18	S 48 E 41		
30	do	15	S 30 N 23		
31	do	14	S 44 N 23		
32	do	16	S 49 E 42		
33	do	10	S 54 N 38		
34	do	12	S 54 E 20		
35	do	14	S 51 N 22		
36	do	12	S 51 E 18		
37	do	30	S 45 E 8		
38	do	41	S 45 N 21		
39	do	14	S 48 E 8		
40	do	8	S 41 N 17		
41	do	10	S 64 E 42		
42	do	6	S 68 N 6		
43	do	9	S 66 N 14		
44	do	10	S 66 E 15		
45	do	18	S 48 N 20		
46	do	8	S 62 E 25		
47	do	10	S 45 N 16		
48	do	14	S 44 E 8		
49	do	30	S 33 E 23		
50	do	8	S 52 N 38		
51	do	12	S 58 N 36		
52	do	24	S 42 E 17		
53	do	24	S 45 N 20		
54	do	26	S 41 E 26		
55	do	12	S 44 N 41		
56	do	30	S 43 E 34		
57	do	10	S 40 E 25		
58	do	12	S 30 N 28		
59	do	15	S 50 N 11		
60	do	10	S 42 E 17		
61	do	12	S 49 N 12		
62	do	12	S 47 E 38		
63	do	18	S 49 E 50		
64	do	20	S 47 N 13		

Interior Quarter Section Corners

Section	Bearing	Distance	Course	Point	Quality of the Soil
1 to 2	do				
2	do				
3	do				
4	do				
5	do				
6	do				
7	do				
8	do				
9	do				
10	do				
11	do				
12	do				
13	do				
14	do				
15	do				
16	do				
17	do				
18	do				
19	do				
20	do				
21	do				
22	do				
23	do				
24	do				
25	do				
26	do				
27	do				
28	do				
29	do				
30	do				
31	do				
32	do				
33	do				
34	do				
35	do				
36	do				
37	do				
38	do				
39	do				
40	do				
41	do				
42	do				
43	do				
44	do				
45	do				
46	do				
47	do				
48	do				
49	do				
50	do				
51	do				
52	do				
53	do				
54	do				
55	do				
56	do				
57	do				
58	do				
59	do				
60	do				
61	do				
62	do				
63	do				
64	do				

Interior Quarter Section Corners

Section	Bearing	Distance	Course	Point	Quality of the Soil
1 to 2	do				
2	do				
3	do				
4	do				
5	do				
6	do				
7	do				
8	do				
9	do				
10	do				
11	do				
12	do				
13	do				
14	do				
15	do				
16	do				
17	do				
18	do				
19	do				
20	do				
21	do				
22	do				
23	do				
24	do				
25	do				
26	do				
27	do				
28	do				
29	do				
30	do				
31	do				
32	do				
33	do				
34	do				
35	do				
36	do				
37	do				
38	do				
39	do				
40	do				
41	do				
42	do				
43	do				
44	do				
45	do				
46	do				
47	do				
48	do				
49	do				
50	do				
51	do				
52	do				
53	do				
54	do				
55	do				
56	do				
57	do				
58	do				
59	do				
60	do				
61	do				
62	do				
63	do				
64	do				

HO

28 N, R 15 E. 2^d Mer.

A copy of the original subdivision of fractional sections
made under the provisions of the Act of 5th Apr. 1832.


Surveyor Genl's office }
Cin. Aug. 24. 1833 }

M. T. Williams
Sur. Genl.

First Principal Meridian or State line

1.
34.78
Sec 35.
2.
35.30

T28N, R15E, T. Meridian



First Principal Meridian to State line

Sec. 36
35.30

Ent. J. H. Wayne Vol. 9. L.C.

A copy of subdivisions of fractional sections made
under the provisions of the Act of the 5th April 1832.
Sur. Genl. Office }
Given Sept. 10. 1833. } M. T. Williams
Sur. Genl.

Recd with Jas. L. Little of March 18. 1842

T. 28 N. R. 15 E. 2nd Mer.

T. 29 N. R. 15 E. 2nd Mer.

A 34.36	A 33.04	A 33.74	A 33.46	A 33.04	A 32.48	A 32.21	A 32.23
---------	---------	---------	---------	---------	---------	---------	---------

State Line between Ohio & Indiana.

A 24.93	A 26.63	A 28.09	A 29.81	A 30.81	A 32.59
---------	---------	---------	---------	---------	---------

State Line, &c.

Cont'd in Vol. 9 & 15
E. L.

A true copy from record

Surveyor General's Office
Cincinnati March 18. 1842

E. L. L. L.
Sur. Genl.

Township N. XXVIII North, Range N. XV East 2^d Mer

185.72	191.20	195.00	196.80	196.95	196.06	197.66	197.90
180.00	185.11	185.11	185.11	185.11	185.11	185.11	185.11
19033	19034	19035	19036	19037	19038	19039	19040
19041	19042	19043	19044	19045	19046	19047	19048
19049	19050	19051	19052	19053	19054	19055	19056
19057	19058	19059	19060	19061	19062	19063	19064
19065	19066	19067	19068	19069	19070	19071	19072
19073	19074	19075	19076	19077	19078	19079	19080
19081	19082	19083	19084	19085	19086	19087	19088
19089	19090	19091	19092	19093	19094	19095	19096
19097	19098	19099	19100	19101	19102	19103	19104
19105	19106	19107	19108	19109	19110	19111	19112
19113	19114	19115	19116	19117	19118	19119	19120
19121	19122	19123	19124	19125	19126	19127	19128
19129	19130	19131	19132	19133	19134	19135	19136
19137	19138	19139	19140	19141	19142	19143	19144
19145	19146	19147	19148	19149	19150	19151	19152
19153	19154	19155	19156	19157	19158	19159	19160
19161	19162	19163	19164	19165	19166	19167	19168
19169	19170	19171	19172	19173	19174	19175	19176
19177	19178	19179	19180	19181	19182	19183	19184
19185	19186	19187	19188	19189	19190	19191	19192
19193	19194	19195	19196	19197	19198	19199	19200

3430
857
42,571

788.56
1304.56
729.34
2822.46

Wm. Adams & Co.

A true copy from the original on file in this office.
Surveyor General's Office, Sept 10th 1882.
John A. Sullivan Sur. Gen.